

- 3 Place the battery blank in the CR3500 bar code reader. (Figure 5)



Figure 5

- 4 Plug the USB cable into the reader and computer. (Figure 6 and 7)



Figure 6



Figure 7

- 5 Power on the reader by pressing and holding down the right red button. (Figure 8)



Figure 8

- 6 Press the soft key on the reader, under 'Upload'. (Figures 9 and 10)



Figure 9



Figure 10

- 7 Confirm the USB Cable is connected to both the reader and computer, and press the soft key under 'Yes'. (Figures 10 and 11)




Figure 11

- 8 Open up the FileUploader folder you saved to the desktop, and double click on the C002880_FileUploader Icon, and select 'Run'.
- 9 The connection window will open up on your desktop, select USBHID, then click OK. (Figure 12)



Figure 12

- 10 Select the date of the file you wish to upload (data files are in the yearmonthdayhour.rec format) Make sure 'erase after upload' is **NOT** selected, and click upload. The reader will beep twice to indicate the upload is complete. (Figure 13)




Figure 13

Note: DO NOT select 'erase after upload'.

- 11 Files are stored in your Windows Temp directory. To open the folder, select 'Open'. (Figure 14)




Figure 14

11 Unplug the USB Cable from the CR3500 and the computer, and remove the battery blank from the reader.

12 Attach the CR3500 to the handle. (Figures 15, 16 and 17)



Figure 17 - put the connector into the reader



Figure 16 - make sure the tab on the handle (Figure 16a) is inserted into the slot on the reader (Figure 16b)



Figure 16a



Figure 16b

Press down on the reader until you hear a click - verify the tab is locked in place. (Figure 17)



Figure 17

13 Using the allen wrench provided, replace the screws and washers removed in Step 2 to secure the CR3500 bar code reader to the handle. (Figure 18)



Figure 18

14 Power on the reader by pressing and holding down the right red button. (Figure 19)




Figure 19

code | 14940 S. Pony Express Rd. Bluffdale, UT 84065
www.codecorp.com (801) 495-2200

Age Verification Download Quickstart Guide - DABC Use Only

Included:



Allen wrench and extra set of screws and washers



USB Cable



Battery Blank

Getting Started:

1 Download the CodeXML™ File Uploader program from the Code Corporation website at: <http://www.codecorp.com/fileuploadereula.php>

- Select 'Agree' to End License User Agreement,
- Save to your desktop by selecting 'Save'

2 Using the allen wrench provided, remove the screws and washers securing the CR3500 bar code reader to the handle. (Figure 1)



Figure 1

3 Remove the CR3500 from the handle. (Figures 2, 3 and 4)



Figure 2 - pull the tab to release the reader from the handle



Figure 3 - pull the reader away from the handle



Figure 4 - pull the connector on the handle away from the reader to release the reader